


# PHOTO PROGRESS REPORT

### DG Stack Work is in Progress



Tower A, Entrance lobby Finishing work





# Retaining wall, Excavation work for Foundation PCC



Basement, Cable tray Support Work










Tower-G, External Putty Work

### Retaining Wall, Soil Filling Work




#### Electrical Panel Delivered on Site



### All Pump placed, WTP work is in progress



Ramp Construction is in progress



# School Finishing work is in progress

